

Handwritten:
B+C3-1

28 January 1987

MEMORANDUM FOR: Chief, Physical Security Division, OS

FROM:

Chief, New Building Project Office, OL

SUBJECT: Security Barriers for the Turkey Run Road Entrance

1. The site plan for constructing the renovated Turkey Run Road entrance to the Headquarters compound identifies a requirement for the installation of two security barriers. The Bid Package 2 contractor is currently constructing the roadway around the Turkey Run Road entrance and requests the barriers so that the roadway may be completed. The contractor also requests information relating to the electrical conduit and/or sensors required to operate the barriers.

2. We understand there have been problems with the operation of the entrance security barriers and the Office of Security (OS) is reviewing whether the barriers should be used in the future. With this in mind and so that the contractor may complete the Turkey Run entrance roadway, please advise whether OS still wishes to have barriers installed at the Turkey Run entrance. If barriers are to be installed at this entrance, please advise how these barriers can be provided to the contractor and identify a point of contact for addressing the contractor's questions about sensors and electrical conduit.

3. Please provide the above information by 6 February 1987 to avoid delays in construction.

OL/NBPO 28Jan87
Orig - Adse
1 - OL/NBPO Subject
1 - OL/NBPO Chrono
1 - OL Files

OL 2004-87